

**Mainline 6B 2012 Maintenance and Rehabilitation & Line 6B Replacement Projects**  
**IDEM Water Quality Certification Independent Environmental Monitor Weekly Observation Report**

Observation Dates:	02/17/14 thru 02/22/14
IEM Name:	Glen Chandler- Eric Sorenson
Waterbody Identification Number(s):	s-483-a,
Wetland Identification Number(s):	w-485-x, w-517-f.
Enbridge Land Tract Identification Number(s):	n-618-1, n-619-8, n-626-6, n-648-2A.
County(s): St.Joseph, LaPorte, Porter	Porter and LaPorte
<p>02/17/14: Off E.1100N. rd. testing work continues at Sta.#1502+24, Tract n-626-6. The Meridian rd. Co. Drain repair HDD progress continues. West of w-485-x an anomaly dig was observed, Sta.#1057+38, Tract n-619-8. Sheet pile removal was observed at s-483-a, Sta.#971+05, Tract n-618-1 and Salt Creek was found to be clean and clear. 02/18/14: East of w-517-f tie-in work observed, Sta.#2800+12, tract n-648-2A. Equipment demobilization and clean-up was observed at s-483-a, Sta.#971+05, Tract n-618-1. Marty Maupin of IDEM met with IEM to walk through pipeline monitoring area and confirm substantial completion of pipeline crossed wetland and waterbody resources. IDEM reports of restoration activities will be given by the Environmental team. 02/19/14: The contractor has put the hydro testing at sta#1500+00, tract N-626-6 on standby while anomaly repairs are being made. A dig up is being conducted near sta#1055+00, tract N-619-8. A de watering hay structure was constructed in a near upland area. No environmental concerns at this location. 02/20/14: Hydro testing is being performed on the pipeline. No activity due to safety reasons. 02/21/14: Performed storm water inspections throughout the ROW. 02/22/14: The contractor continues with the hydro testing efforts.</p>	



Off 1100N. Testing work observed, Sta.#1502+24



West of w-485-x anomaly dig observed, Sta.#1057+38



East of w-517-f tie-in work observed, Sta.#2800+12



S-483-a Salt Creek off Hwy 149 clean-up, Sta.#971+05



sta#1500+00\_MP493.5\_hydro testing on stand by\_N-626-6\_N



sta#1055+00\_MP485.1\_N-619-8\_anomaly dig up\_W



sta#1500+00\_MP493.5\_testing procedures continue\_NE

